

Annexure D

BUILDING SAFETY CERTIFICATE

No. 3916/14 mg / 23.

Dated: 17.10.2023,

It is certified that the existing building DABBLE PUBLIC SCHOOL, BANIMARA LK ... (name of the building or premises) at BANIMARA, KANPUR ROAD.....

..... (address) is having block(s)/Floor(s) as per details below:


Detail of Block(s) in school	Block A (1)	Block B (2)	Block (3)	Block (4)	Block (5)	Block (6)
No. of Floor(s) in the Block	Ground + 01	Ground + 01	NA	NA	NA	NA

The building is owned/occupied by DABBLE PUBLIC SCHOOL BANIMARA, LUCKNOW (name of the Institution) have complied with the Building safety requirements in accordance with National Building code Rules, and verified by the officers concerned of C.D:2, PWD, LK..... (Name of Department/ Govt.) on 27.07.2023..... (date of inspection) in the presence of Principal of Dabble Public School, Banimara, Lucknow (name and addresses of the Manager/Secretary or his representative) and that the building/premises is fit for occupancy for running school with effect from 17.10.2023, for a period of years in accordance with rule and subject to compliance of the specific conditions as appended.

1. Time to time maintenance of the building as per requirement.
2. Presently building has two floors that is ground floor & first floor, in future, if school plans to construct more floor in this building, a fresh application
3. would be submitted by the school for the N.B.C. Code 2005
- 4.

Issued on 17.10.2023..... at Lucknow..... by

* Strike out whichever is not applicable. In case of block is more than six use separate sheet for detail.

Signature with Seal : 

Name : अविशासी अविष्ठा

Designation : निर्माण खण्ड-2, लोकोपनिधिक
लखनऊ

Name & Address of Department/ Office: _____